Appro	ed For Release 2006/10/06	CIA-RDP78T05929A0009000100)7-4 2:
		7 JUNE 1965	
**		PAGE_6	

SELECTED SITES, LAUNCH GROUP "L" TYURATAM MISSILE TEST CENTER, USSR

1.	REVEALED 7 AREAS OF CONSTRUCTION ACTIVITY AT
	THE WEST END OF THE RANGEHEAD AT THE TIMTO IN THE VICINITY OF
	LAUNCH COMPLEXES "F", "G", AND "K". THESE AREAS WERE EVALUATED AS
	A POSSIBLE LAUNCH GROUP UNDER CONSTRUCTION. SUBSEQUENT COVERAGE
	BY 3 KH MISSIONS RESULTED IN THE CONFIRMATION OF THE ORIGINAL 7 AREAS
	OF CONSTRUCTION ACTIVITY AS TYPE IIID SINGLE SILO LAUNCH SITES AND THE
	IDENTIFICATION OF 3 ADDITIONAL SITES, ALSO TYPE IIID, MAKING A TOTAL
	OF 10. A CIRCULAR PATTERN FORMED BY 6 SITES WAS APPARENT WITH A
	PROBABLE CONTROL FACILITY AND A SEVENTH SITE AT THE APPROXIMATE
	CENTER; 3 SITES WERE LOCATED OUTSIDE THE CIRCLE.
	LAUNCH SITE L1 WAS FIRST IDENTIFIED ON
	WHICH MISSION CONSTRUCTION ACTIVITY COULD BE INITIALLY OBSERVED.
	SITES L4, L6, L9, AND L10 WERE FIRST OBSERVED ON
	CONSTRUCTION ACTIVITY AT THESE SITES WAS FIRST OBSERVABLE ON
	RESPECTIVELY. THERE WAS NO EVIDENCE OF ACTIVITY AT THESE SITES AS
	OF THE FOLLOWING MISSIONS:
2.	THIS MISSION REVEALS THAT 9 OF THE 10 SITES ARE COVERED. ALL ARE

DOUBLE-SECURED AND HAVE A MOUNDED EARTH LEVEL ACCESS TO THE SILO.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.


2

2

TCP SEC.II

7 June 1965

Page 7



AT LAUNCH SITE 11, A CONTROL BUNKER IS UNDER CONSTRUCTION
ADJACENT TO THE "L"-SHAPED ELECTRONIC FACILITY. SMALL SILOS ARE
UNDER CONSTRUCTION AT THE EXTREMITIES AND AT THE INTERSECTION OF
OF THE LEGS OF THE ELECTRONIC FACILITY. THE LAUNCH SILO IS BACKFILLED, BUT THE LEVEL ACCESS IS NOT PAVED. CABLE DITCHING IS APPARENT IN THE AREA.

LAUNCH SITE L6 IS BACKFILLED WITH THE EXCEPTION OF ONE SIDE OF THE SILO. PAVING OF THE LEVEL ACCESS IS IN PROGRESS; AND 3 UNIDENTIFIED STRUCTURES ARE NEWLY OBSERVED. LAUNCH SITES L4, L9, AND L10 APPEAR TO BE COMPLETELY BACKFILLED, AND A PORTION OF THE LEVEL ACCESS AT EACH SITE HAS BEEN PAVED ON EITHER SIDE OF THE SILO. UNIDENTIFIED STRUCTURES ARE ALSO PRESENT AT LAUNCH SITE L4, AND CABLE DITCHING IS OBSERVED AT LAUNCH SITES L9 AND L10.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.